Department of Nuclear Science and Engineering

# ELECTRICAL SAFETY

for Staff and Students in NSE Instructional Laboratories

#### NEVER WORK ALONE

If you are working with energized circuits or equipment over 50 volts peak, make sure that at least one other person can see you and hear you. In case of emergency **DIAL 100** from any phone; and, notify the stock clerk on duty.

### **VOLTAGE RULES**

All NSE Instructional Laboratories lab kit voltages are **below 50 volts peak**. (OSHA permits "unqualified persons" to work on such circuits with "awareness-type" training.)

If you intend to work on a project using power sources **over 50 volts peak**, you must **secure permission** and receive **specific training** from your Instructor, TA, or Lab Technical Personnel **before** any work on the project begins.

#### PREVENT ACCIDENTS: FOLLOW THIS ADVICE

- Never hurry. Work deliberately and carefully.
- Connect to the power source LAST.
- If you are working with a lab kit that has internal power supplies, turn the main power switch OFF before you begin work on the circuits. Wait a few seconds for power supply capacitors to discharge. These steps will also help prevent damage to circuits.
- If you are working with a circuit that will be connected to an external power supply, turn the power switch of the external supply OFF before you begin work on the circuit.
- Check circuit power supply voltages for proper value and for type (DC, AC, frequency) before energizing the circuit.
- Do not run wires over moving or rotating equipment, or on the floor, or string them across walkways from bench-to-bench.
- Remove conductive watch bands or chains, finger rings, wrist watches, etc., and do not use metallic pencils, metal or metal edge rulers, etc. when working with exposed circuits.
- When breaking an inductive circuit open the switch with your left hand and turn your face away to avoid danger from any arc which may occur across the switch terminals.
- When using large electrolytic capacitors be sure to wait long enough (approximately five time constants) for the capacitors to discharge before working on the circuit.
- All conducting surfaces intended to be at ground potential should be connected together.

## ADDITIONAL CAUTIONS

- Any equipment used in the laboratories must be equipped with a standard three-prong AC plug or a two-pronged polarized plug.
- All exposed non-current-carrying metal parts of fixed and portable equipment that may accidentally become energized should be grounded.
- All electrical equipment or apparatus that may require frequent maintenance must be capable of being completely disconnected from the power source.
- Do not bring into the lab or use in the lab equipment that does not conform to these rules without specific permission from your instructor, TA, or Lab Technical Personnel.

## LASER LABORATORY SAFETY

- Students who intend to use laser systems **must** read the Radiation Protection Office (RPO) Laser Safety Program Handbook **before** working with lasers. Copies of this handbook are available from the 38-501 Stockroom.
- Students must attend the RPO Safety Training Seminar if they will be using Class III or IV lasers.

## **RIGHT-TO-KNOW LAW (OSHA HAZARD COMMUNICATION STANDARD)**

- OSHA requires MIT to inform employees (and MIT requires students be informed the same as employees) about potential exposure to hazardous chemicals and about the Institute's Hazard Communication Program and the requirements of the Federal Right-to-Know Law. Your supervisor/instructor and department are responsible for providing you with safety information and/or training on:
  MIT Policies and Procedures on Environmental Health & Safety
  Material Safety Data Sheets
  Labeling requirements for all hazardous materials
  The location of the hazardous material inventory of your work area
  Any operations in your work area that involve hazardous chemicals and the associated health and safety hazards
  Safety precautions and procedures
  Emergency procedures
- The OSHA Hazard Communication Standard and MIT's written Hazard Communication Program are on file in the MIT Safety Office and will be made available to any member of the MIT Community, upon request.

## **QUESTIONS ABOUT WORK/SCHOOL SAFETY**

• Any questions about work or school safety should be brought to the attention of your immediate supervisor or instructor. If problems arise that cannot be solved at this level, you should contact the NSE administrator.

# BASIC ELECTRICAL SAFETY PRACTICES

The Institute requires everyone who uses electrical equipment to understand these safety precautions to comply with the OSHA Electrical Safety-Related Work Practices standard and MIT's electrical safety policies. The following safe work practices can prevent electrical shock. Contact your supervisor for additional safety training if your job involves repairing, installing or working on energized parts.

A. Safe Work Practices

- 1. Turn off and unplug equipment (instead of relying on interlocks that can fail) before removing the protective cover to clear a jam, replace a part, adjust or troubleshoot. Ask a qualified person to do the work if it involves opening equipment and creating an exposure to energized parts operating at 50 volts or more.
- 2. Don't use an electrical outlet or switch if the protective cover is ajar, cracked or missing. Call FIXIT and report this.
- 3. Only use DRY hands and tools and stand on a DRY surface when using electrical equipment, plugging in an electric cord, etc.
- 4. Never put conductive metal objects into energized equipment.
- 5. Always pick up and carry portable equipment by the handle and/or base. Carrying equipment by the cord damages the cord's insulation.
- 6. Unplug cords from electrical outlets by pulling on the plug instead of pulling on the cord.
- 7. Use extension cords temporarily. The cord should be appropriately rated for the job.
- 8. Use extension cords with 3 prong plugs to ensure that equipment is grounded.
- 9. Never remove the grounding post from a 3 prong plug so you can plug it into a 2 prong, wall outlet or extension cord.
- 10. Re-route electrical cords or extension cords so they aren't run across the floor, under rugs or through doorways, etc. Stepping on, pinching or rolling over a cord will break down the insulation and will create shock and fire hazards.
- 11. Don't overload extension cords, multi-outlet strips and wall outlets.
- 12. Heed the warning signs, barricades and/or guards that are posted when equipment or wiring is being repaired or installed or if electrical components are exposed.
- B. *Check for Unsafe Conditions* (either before or while you're using equipment:)
- 1. Is the cord's insulation frayed, cracked or damaged, exposing the internal wiring?
- 2. Are the plug's prongs bent, broken or missing, especially the third prong?
- 3. Is the plug or outlet blackened by arcing?
- 4. Was liquid spilled on or around the equipment?
- 5. Are any protective parts (or covers) broken, cracked or missing?
- 6. Do you feel a slight shock when you use the equipment?
- 7. Does the equipment or the cord overheat when it is running?
- 8. Does the equipment spark when it is plugged in or when switches or controls are used?

### C. If you observe any of these unsafe conditions:

- 1. Don't use (or stop using) the equipment.
- 2. Tag/label the equipment UNSAFE--DO NOT USE and describe the problem.
- 3. Notify your supervisor, FIXIT or the service company, as appropriate.

Electrical safety is for everyone because even contact with the standard 117 volt electrical circuits, which we constantly use, can be lethal under certain conditions.